
ACETONE


Chemical Formula: C₃H₆O

CAS Registry Number: 67-64-1

NOTICE: THE INFORMATION BELOW IS BELIEVED TO BE ACCURATE AND REPRESENTS THE BEST INFORMATION CURRENTLY AVAILABLE TO US. HOWEVER, WE MAKE NO WARRANTY OF MERCHANTABILITY OR ANY OTHER WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO SUCH INFORMATION, AND WE ASSUME NO LIABILITY RESULTING FROM ITS USE. USERS SHOULD MAKE THEIR OWN INVESTIGATIONS TO DETERMINE THE SUITABILITY OF THE INFORMATION FOR THEIR PARTICULAR PURPOSES. IN NO EVENT SHALL SAMCHEM PRASANDHA BE LIABLE FOR ANY CLAIMS, LOSSES, OR DAMAGES OF ANY THIRD PARTY OR LOST PROFITS OR ANY SPECIAL, INDIRECT, INCIDENTAL, CONSEQUENTIAL OR EXEMPLARY DAMAGES, HOWSOEVER ARISING, EVEN IF SAMCHEM PRASANDHA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

PRODUCT INFORMATION





Synonyms:

- 2-Propanone
- Aceton
- acetona
- Acetone
- Acetone A.R
- DIMETHYL KETONE
- Dimethylformaldehyde
- Methyl ketone
- NSC 135802
- Propanone
- Pyroacetic ether
- UN 1090
- UN 1090
- β-Ketopropane

Description

Acetone, the lowest molecular weight member of the ketone family of solvents, is a low boiling, fast evaporating, colorless, stable liquid. Because acetone possesses excellent solvent power for most natural and synthetic resins including acrylics, vinyl polymers, nitrocellulose, cellulose acetate, and other cellulose derivatives, it is a popular and effective low-boiling solvent for surface coating applications. Since most waxes, oils, fats, greases, and dye materials are soluble in acetone, it is ideally suited for extraction and other end uses.

Property	Units	Min	Max	N	Method
Purity	%w	99.5			ASTM D2804
Isopropyl Alcohol	%w		0.05		Q-044-S
Methanol	%w		0.05		Q-044-S
Permanganate Fading Time @25C	min	120			ASTM D1363
Solubility in Water @25C	pass				ASTM D1722
Acidity as acetic acid	%w		0.002		ASTM D1613
Color, Pt-Co			5		ASTM D1209
Water	%w		0.50		ASTM D1364
Appearance	Clear & Free From Suspended Matter				ASTM D4176
Specific Gravity @20C		0.7910	0.7925	1	ASTM D4052
Specific Gravity @25C		0.7865	0.7880	1	ASTM D4052
Distillation Range	°C	0.8		1	ASTM D1078
Distillation, incl 56.1C	Pass			1	ASTM D1078
Nonvolatile Residue	mg/100ml		1	1	ACS
Aldehydes as HCHO	%w		0.002	1	ACS
Alkalinity as NH3	%w		0.001	1	ASTM D1614
Organic Volatile Impurities	Pass			1	NF
Benzene	ppmw		30		Q-044-S

Production Proccess

Acetone is produced directly or indirectly from propene. Most commonly, in the cumene process, benzene is alkylated with propene and the resulting <u>cumene</u> (isopropylbenzene) is oxidized to give phenol and acetone:

 $C_6H_5CH(CH_3)_2 + O_2 \rightarrow C_6H_5OH + (CH_3)_2CO$

This conversion entails the intermediacy of cumene hydroperoxide, $C_6H_5C(OOH)(CH_3)_2$.

Acetone is also produced by the direct oxidation of propene with a Pd(II)/Cu(II) catalyst, akin to the Wacker process.

Stability and Reactivity

Stability:

Stable under ordinary conditions of use and storage.

Hazardous Decomposition Products:

Carbon dioxide and carbon monoxide may form when heated to decomposition.

Hazardous Polymerization:

Will not occur.

Incompatibilities:

Concentrated nitric and sulfuric acid mixtures, oxidizing materials, chloroform, alkalis, chlorine compounds, acids, potassium t-butoxide.

Conditions to Avoid:

Heat, flames, ignition sources and incompatibles.

Hazards Identification

Emergency Overview

DANGER! EXTREMELY FLAMMABLE LIQUID AND VAPOR. VAPOR MAY CAUSE FLASH FIRE. HARMFUL IF SWALLOWED OR INHALED. CAUSES IRRITATION TO SKIN, EYES AND RESPIRATORY TRACT. AFFECTS CENTRAL NERVOUS SYSTEM.

SAF-T-DATA^(tm) Ratings (Provided here for your convenience)

Health Rating: 2 - Moderate

Flammability Rating: 3 - Severe (Flammable)

Reactivity Rating: 0 - None Contact Rating: 3 - Severe

Lab Protective Equip: GOGGLES & SHIELD; LAB COAT & APRON; VENT HOOD; PROPER GLOVES; CLASS B

EXTINGUISHER

Storage Color Code: Red (Flammable)

Potential Health Effects

Inhalation:

Inhalation of vapors irritates the respiratory tract. May cause coughing, dizziness, dullness, and headache. Higher concentrations can produce central nervous system depression, narcosis, and unconsciousness.

Ingestion:

Swallowing small amounts is not likely to produce harmful effects. Ingestion of larger amounts may produce abdominal pain, nausea and vomiting. Aspiration into lungs can produce severe lung damage and is a medical emergency. Other symptoms are expected to parallel inhalation.

Skin Contact:

Irritating due to defatting action on skin. Causes redness, pain, drying and cracking of the skin.

Eye Contact:

Vapors are irritating to the eyes. Splashes may cause severe irritation, with stinging, tearing, redness and pain.

Chronic Exposure:

Prolonged or repeated skin contact may produce severe irritation or dermatitis.

Aggravation of Pre-existing Conditions:

PT. Samchem Prasandha Taman Palem Lestari Block A30 No. 26 Cengkareng - Jakarta 11730 - Indonesia Phone: 62-21-55952991 (hunting)

Fax : 62-21-55952994

Use of alcoholic beverages enhances toxic effects. Exposure may increase the toxic potential of chlorinated hydrocarbons, such as chloroform, trichloroethane.

First Aid Measures

Inhalation:

Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get medical attention.

Ingestion:

Aspiration hazard. If swallowed, vomiting may occur spontaneously, but DO NOT INDUCE. If vomiting occurs, keep head below hips to prevent aspiration into lungs. Never give anything by mouth to an unconscious person. Call a physician immediately.

Skin Contact:

Immediately flush skin with plenty of water for at least 15 minutes. Remove contaminated clothing and shoes. Get medical attention. Wash clothing before reuse. Thoroughly clean shoes before reuse.

Eve Contact:

Immediately flush eyes with plenty of water for at least 15 minutes, lifting upper and lower eyelids occasionally. Get medical attention.

Fire Fighting Measures

Fire:

Flash point: -20C (-4F) CC

Autoignition temperature: 465C (869F) Flammable limits in air % by volume:

lel: 2.5; uel: 12.8

Extremely Flammable Liquid and Vapor! Vapor may cause flash fire.

Explosion:

Above flash point, vapor-air mixtures are explosive within flammable limits noted above. Vapors can flow along surfaces to distant ignition source and flash back. Contact with strong oxidizers may cause fire. Sealed containers may rupture when heated. This material may produce a floating fire hazard. Sensitive to static discharge.

Fire Extinguishing Media:

Dry chemical, alcohol foam or carbon dioxide. Water may be ineffective. Water spray may be used to keep fire exposed containers cool, dilute spills to nonflammable mixtures, protect personnel attempting to stop leak and disperse vapors.

Special Information:

In the event of a fire, wear full protective clothing and NIOSH-approved self-contained breathing apparatus with full facepiece operated in the pressure demand or other positive pressure mode.

<u>Accidental Release Measures</u>

Ventilate area of leak or spill. Remove all sources of ignition. Wear appropriate personal protective equipment as specified in Section 8. Isolate hazard area. Keep unnecessary and unprotected personnel from entering. Contain and recover liquid when possible. Use non-sparking tools and equipment. Collect liquid in an appropriate container or absorb with an inert material (e. g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not use combustible materials, such as saw dust. Do not flush to sewer! If a leak or spill has not ignited, use water

Fax: 62-21-55952994

spray to disperse the vapors, to protect personnel attempting to stop leak, and to flush spills away from exposures. US Regulations (CERCLA) require reporting spills and releases to soil, water and air in excess of reportable quantities.

Handling and Storage

Protect against physical damage. Store in a cool, dry well-ventilated location, away from any area where the fire hazard may be acute. Outside or detached storage is preferred. Separate from incompatibles. Containers should be bonded and grounded for transfers to avoid static sparks. Storage and use areas should be No Smoking areas. Use non-sparking type tools and equipment, including explosion proof ventilation. Containers of this material may be hazardous when empty since they retain product residues (vapors, liquid); observe all warnings and precautions listed for the product.

Exposure Controls/Personal Protection

Airborne Exposure Limits:

Acetone:

- -OSHA Permissible Exposure Limit (PEL): 1000 ppm (TWA)
- -ACGIH Threshold Limit Value (TLV): 500 ppm (TWA),

750 ppm (STEL) A4 - not classifiable as a human carcinogen

Ventilation System:

A system of local and/or general exhaust is recommended to keep employee exposures below the Airborne Exposure Limits. Local exhaust ventilation is generally preferred because it can control the emissions of the contaminant at its source, preventing dispersion of it into the general work area. Please refer to the ACGIH document, *Industrial Ventilation*, *A Manual of Recommended Practices*, most recent edition, for details.

Personal Respirators (NIOSH Approved):

If the exposure limit is exceeded and engineering controls are not feasible, a half-face organic vapor respirator may be worn for up to ten times the exposure limit, or the maximum use concentration specified by the appropriate regulatory agency or respirator supplier, whichever is lowest. A full-face piece organic vapor respirator may be worn up to 50 times the exposure limit, or the maximum use concentration specified by the appropriate regulatory agency or respirator supplier, whichever is lowest. For emergencies or instances where the exposure levels are not known, use a full-face piece positive-pressure, air-supplied respirator. WARNING: Air-purifying respirators do not protect workers in oxygen-deficient atmospheres.

Skin Protection:

Wear impervious protective clothing, including boots, gloves, lab coat, apron or coveralls, as appropriate, to prevent skin contact.

Eye Protection:

Use chemical safety goggles and/or a full face shield where splashing is possible. Maintain eye wash fountain and quick-drench facilities in work area.

Other Information

NFPA Ratings: Health: 1 Flammability: 3 Reactivity: 0

Label Hazard Warning:

DANGER! EXTREMELY FLAMMABLE LIQUID AND VAPOR. VAPOR MAY CAUSE FLASH FIRE. HARMFUL IF SWALLOWED OR INHALED. CAUSES IRRITATION TO SKIN, EYES AND RESPIRATORY TRACT. AFFECTS CENTRAL

5 Fax: 62-21-55952994



NERVOUS SYSTEM.

Label Precautions:

Keep away from heat, sparks and flame. Keep container closed. Use only with adequate ventilation. Wash thoroughly after handling. Avoid breathing vapor.

Avoid contact with eyes, skin and clothing.

Label First Aid:

Aspiration hazard. If swallowed, vomiting may occur spontaneously, but DO NOT INDUCE. If vomiting occurs, keep head below hips to prevent aspiration into lungs. Never give anything by mouth to an unconscious person. Call a physician immediately. If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. In case of contact, immediately flush eyes or skin with plenty of water for at least 15 minutes. Remove contaminated clothing and shoes. Wash clothing before reuse. In all cases, get medical attention.

Applications

Acetone finds application in the manufacture of acetate rayon, photographic films, smokeless powder, artificial leather, dopes, cements and paint remover and as an absorbent for compressed acetylene. A large quantity of acetone also serves as a raw material and/or intermediate in the production of other chemicals, such as methacrylate resins, pharmaceuticals, bisphenol A and solvents.

Phone : 62-21-55952991 (hunting) Fax : 62-21-55952994